

REQUEST FOR PRICE QUOTES – The Greater Bridgeport Regional Planning Agency on behalf of Bridgeport, Monroe and Trumbull is requesting price quotes for various equipment to be used in the maintenance of the Housatonic Railroad Trail. The equipment will be purchased using a grant from the state of Connecticut under the Regional Performance Incentive Program. The following equipment will be purchased:

- Bobcat 5600 Turbo Toolcat, 56 HP turbo diesel engine with deluxe road package with cab enclosure with heater/air conditioning, high flow aux hydraulics, heavy duty battery, attachment control kits and 62" general purpose bucket;
- Attachments for the Bobcat 5600 Turbo Toolcat, including 68" angle broom, 68" brushcat rotary cutter, 80 gallon sprayer with wiring harness, nozzle spray kit for water kit and plumbing kit, tilt-tatch, SG 60 stump grinder and 5B landscape rake;
- Enclosed cargo trailer 8'x20' to store and transport the Bobcat 5600 Turbo Toolcat;
- Various portable equipment including professional backpack blower, profession 20" bar chainsaw, professional fixed length pole pruner, and professional trimmer/brush cutter;
- Two X2 Adventure Segways;
- Trail counting equipment to count number of hikers and bicyclists along the trail.

Vendors may provide price quotes for the entire package of equipment or selectively bid on components. However, vendors are requested to provide details, including full descriptions and product numbers, on the specific equipment being bid. Also, the Bobcat 5600 Turbo Toolcat with listed accessories and attachments must be bid as a complete package. The purchase of this equipment is exempt from State of Connecticut Sales Taxes.

Please submit price quotes to the Greater Bridgeport RPA, Attention Mark Nielsen, Executive Director, 525 Water Street, Bridgeport, CT 06604 or via email at [mnielsen@gbrpa.org](mailto:mnielsen@gbrpa.org) by October 13, 2009. The GBRPA and the project Advisory Committee reserves the right to reject any and all price quotes or to waive any informalities, irregularities or technical defects in the quotes.